## Appendix A: Tree Schedule

Tree Nº	Species	Age	Height	Dia	(	Crown Sp	oread (m	)	Life	Cat	Cond	General Observations	Preliminary	RPA	RPA
INº			(m)	(mm)	N	E	s	W	Exp				Management Recommendations	(m²)	Radiu s (m)
G1	Hawthorn, English Oak, Wild Cherry	М	7 (Avg)	200 (Avg)	/	/	/	/	20+	C2	Fair	Trees offsite. Estimated diameter. Extensive ivy cover prevented a comprehensive VTA.	Monitor ivy cover.	/	2.4
G2	English Oak, Field Maple, Ash, Hazel	М	3 (Avg)	60 (Avg)	/	/	/	/	40+	C2	Fair	Young trees on field boundary. Damage from edge clearing. Estimated diameter.	No works recommended at present.	/	0.7
G3	Holly, Hazel	EM	4 (Avg)	50 (Avg)	/	/	/	/	20+	C2	Fair	Screen of early mature individuals with occasional minor gaps. Ivy cover is extensive throughout, reaching the top of some individuals. Diameter estimated due to ivy preventing access. Ivy limited VTA.	Monitor ivy cover.	/	0.6
G4	Field Maple, Blackthorn, Ash	SM	4 (Avg)	100 (Avg)	/	/	/	/	20+	C2	Fair	Group of close trees with tall grass and bramble. Larger individuals of field maple have significant bark damage. Occasional standing deadwood to 4m. Diameter estimated due to bramble limiting access.	Monitor damaged individuals due to proximity to path.	/	1.2
G5	English Oak, Ash, Hawthorn, Hybrid Black Poplar	EM	8 (Avg)	150 (Avg)	/	/	/	/	20+	C2	Fair	Diameter estimated due to large brambles preventing access.	No works recommended at present.	/	1.8
G6	Hawthorn, Hybrid Black Poplar	SM	5 (Avg)	70 (Avg)	/	/	/	/	20+	C2	Fair	Minor pruning where managed along road for vehicle access. diameter estimated.	No works recommended at present.	/	0.8
G7	English Oak, Field Maple, Wild Cherry	EM	8 (Avg)	200 (Avg)	/	/	/	/	20+	C2	Fair	Minor pruning where group has been managed along the road boundary for vehicle access. Diameter estimated.	No works recommended at present.	/	2.4

Tree Nº	Species	Age	Height (m)	Dia (mm)	C	Crown Sp	oread (m	)	Life Exp	Cat	Cond	General Observations	Preliminary Management	RPA (m²)	RPA Radiu
					N	E	S	W					Recommendations		s (m)
G8	Holly, Field Maple, Ash, Silver Birch, Common Alder	M	10 (Avg)	400 (Avg)	/	/	/	/	20+	C2	Fair	Trees away from boundary within school grounds. Good form and structure. Estimated diameter as no access.	No works recommended at present.	/	4.8
H1	Holly, Cherry Laurel, Hazel	M	1 (Avg)	50 (Avg)	/	/	/	/	20+	C2	Fair	Garden hedge with a mix of species. Continuous.	No works recommended at present.	/	0.6
H2	Hazel	M	2 (Avg)	50 (Avg)	/	/	/	/	20+	C2	Fair	Hedge with a mix of species. Continuous. Pruning damage typical of a managed hedgerow.	No works recommended at present.	/	0.6
НЗ	Hazel, Holly, Field Maple, Ash, Purging buckthorn, English Oak	М	2	50 (Avg)	1	1	1	1	20+	C2	Fair	Hedge with a good mix of species. Continuous. Pruning damage typical of a managed hedgerow. Frequent cover of ivy and large brambles. Some low standing deadwood (3m).	No works recommended at present.	/	0.6
H4	Beech	M	2	60 (Avg)	1	1	1	1	20+	C2	Fair	Managed hedgerow on access road. Good form.	No works recommended at present.	/	0.7
H5	Hawthorn	M	2	50 (Avg)	1	1	1	1	20+	C2	Fair	Managed hedgerow on school grounds. Estimated location as not on topographical plan.	No works recommended at present.	/	0.6
T1	English Oak	M	9	500 (Est)	5	5	5	5	20+	C2	Fair	Good form. Minor pruning damage and infrequent deadwood. Estimated diameter as not on site within private garden.	No works recommended at present.	113	6
T2	Field Maple	M	9	250	4	4	1	4	20+	C2	Fair	Not accessible so estimated diameter. On property boundary. Minor pruning and storm damage. Southern Side of canopy limited due to competition with T3. Estimated	No works recommended at present.	28	3

Tree Nº	Species	Age	Height (m)	Dia (mm)	C N	crown Sp	read (m)	) W	Life Exp	Cat	Cond	General Observations	Preliminary Management Recommendations	RPA (m²)	RPA Radiu
					IV	-	3	VV				location as not on topographical plan.	Recommendations		s (m)
Т3	Field Maple	М	10	450 (Est)	4	5	3	5	20+	C2	Fair	Not accessible so estimated diameter. On property boundary. Ivy cover to 6m. Minor pruning and storm damage. Estimated location as not on topographical plan.	No works recommended at present.	92	5.4
T4	Lawson Cypress	EM	8	150 (Est)	1	1	1	1	20+	C2	Fair	Not accessible so estimated diameter. On property boundary. Estimated location not on topographical plan. Very minor ivy cover to 4m.	No works recommended at present.	10	1.8
T5	Field Maple	M	10	530	5	5	6	5	20+	C2	Fair	On property boundary. Minor pruning and storm damage. Minor deadwood on Eastern side at 5m. Estimated location as not on topographical plan.	No works recommended at present.	129	6.4
Т6	Ash	M	10	450 (Est)	6	7	6	3	20+	C2	Fair	Not on site. Estimated diameter. Minor pruning and storm damage especially on southwestern side, epicormic growth abundant. Minor deadwood throughout. Estimated location as not on topographical plan.	No works recommended at present.	92	5.4
Т7	Field Maple	M	6	100 (Est)	2	2	2	2	20+	C2	Poor	Not on site. Estimated diameter. Canopy engulfed by ivy. Estimated location as not on topographical plan.	Monitor ivy progression and tree condition.	5	1.2
Т8	English Oak	M	11	450 (Est)	6	5	4	6	20+	C2	Fair	Estimated diameter due to extensive ivy cover to 7m. Estimated location not on topographical plan.	Monitor ivy progression and tree condition.	92	5.4

Tree Nº	Species	Age	Height (m)	Dia (mm)	N	rown Sp E	read (m) s	) W	Life Exp	Cat	Cond	General Observations	Preliminary Management Recommendations	RPA (m²)	RPA Radiu s (m)
Т9	Holly	M	4	100	0	1	1	1	10+	C2	Poor	Heavily damaged tree within hedgerow. North side canopy absent due to pruning. Estimated location as not on topographical plan.	Monitor ivy progression and tree condition.	5	1.2
T10	Field Maple	EM	5	170	1	1	1	1	10+	C2	Poor	Damaged tree within hedgerow. North side canopy absent to 3m due to pruning. Estimated location as not on topographical plan. Heavy lichen cover.	Monitor ivy progression and tree condition.	13	2
T11	Field Maple	M	12	750 (Est)	5	5	8	6	20+	C2	Fair	Large tree just outside of boundary. Multi-stem. Ivy cover to 9m. Frequent deadwood and storm damage. One stem has failed at a union, exposing heartwood. Estimated diameter and location as not on topographical plan.	Monitor ivy progression and tree condition.	255	9
T12	Field Maple	M	7	450 (Est)	4	1	3	5	20+	C2	Fair	Eastern canopy restricted by T11. Minor ivy cover to 4m. Estimated diameter and location as not on topographical plan.	Monitor ivy progression and tree condition.	92	5.4
T13	Field Maple	M	7	220	2	2	1	2	10+	C2	Poor	Significant pruning on southern side. Areas of absent bark from 3m and extensive lichen cover. Estimated location as not on topographical plan.	Monitor tree condition due to proximity to path.	21	2.6
T14	Ash	M	7	416	5	6	5	6	20+	C2	Fair	Multi-stem. Ivy cover to top of tree. Southern canopy restricted to 3m due to pruning. Estimated diameter and location as not on topographical plan.	Monitor tree condition due to proximity to path.	79	5

Tree Nº	Species	Age	Height (m)	Dia (mm)	C	rown Sp	read (m)	)	Life Exp	Cat	Cond	General Observations	Preliminary Management	RPA (m²)	RPA Radiu
			(111)		N	E	S	W					Recommendations		s (m)
T15	English Oak	M	6	150	2	2	0	2	20+	C2	Fair	Southern canopy restricted due to T16. Estimated location as not on topographical plan.	No works recommended at present.	10	1.8
T16	Hybrid Black Poplar	M	10	220	2	4	4	4	20+	C2	Fair	Good form tree. Minor pruning wounds at 1m. Estimated location as not on topographical plan.	No works recommended at present.	21	2.6
T17	Hybrid Black Poplar	М	11	400	5	6	3	5	20+	C2	Fair	Good form tree. Minor pruning wounds and deadwood at 1m. Estimated location as not on topographical plan.	No works recommended at present.	72	4.8
T18	Hybrid Black Poplar	M	10	200	1	6	4	1	20+	C2	Fair	Good form tree. Estimated location as not on topographical plan.	No works recommended at present.	18	2.4
T19	Hybrid Black Poplar	M	10	220	4	4	1	3	20+	C2	Fair	Good form tree. Estimated diameter due to brambles. Estimated location as not on topographical plan. Minor pruning wounds to 3m on North side.	No works recommended at present.	21	2.6
T20	Hybrid Black Poplar	M	10	292	2	1	4	5	20+	C2	Fair	Estimated diameter due to brambles. Estimated location as not on topographical plan. Multi-stem. Limited northeast canopy due to competition with T19.	No works recommended at present.	38	3.5
T21	Hybrid Black Poplar	M	8	340	2	5	4	5	20+	C2	Fair	Estimated location as not on topographical plan.	No works recommended at present.	53	4.1
T22	Field Maple	M	8	388	4	4	3	4	20+	C2	Fair	Pruned on south side for road access. Multi-stem. Estimated location as not on topographical plan.	No works recommended at present.	69	4.7



Tree Nº	Species Ag	Age	Height (m)	Dia (mm)	Crown Spread (m			)	Life Exp	Cat	Cond	General Observations	Preliminary Management	RPA (m²)	RPA Radiu
				` '	N	E	S	W					Recommendations		s (m)
T23	English Oak	M	10	850 (Est)	7	7	7	7	20+	B2	Fair	Good form tree. Estimated diameter due to being off site within school grounds. Estimated location as not on topographical plan.	No works recommended at present.	327	10.2